



How do you identify utility switching or power factor correction capacitor caused impulses?

